










This Bridge to Bay Trail Wayfinding, Signage and Safety Plan is the result of a nine-month process guided by Friends of the St Clair River, five local trail advisory groups and a steering committee with representation from local, regional and state agencies. Project funding was provided by the Ralph C. Wilson, Jr. Foundation, St Clair County Parks and Recreation Commission and St. Clair County Metropolitan Planning Commission.

Table of Contents

Introduction	5
Algonac	9
Burtchville Twp	19
China Twp	22
Clay Twp	29
Cottrellville Twp	41
East China Twp	47
Fort Gratiot Twp	63
Ira Twp	65
Marine City	68
Marysville	86
New Baltimore	115
Port Huron	117
St Clair	148
St Clair Twp	162



Introduction

This document summarizes recommendations based on meetings with project staff, the steering committee and advisory committees. During these meetings, community stakeholders discussed near-term trail routing, destination sign locations, principal and secondary kiosk locations, and trail parking.

Below is an overview of signs and kiosk discussed.



Principal Kiosk

- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- Requires Footing
- Terrabilt 2-Post Classic Kiosk

The more substantial principal kiosks would be located in trail towns and major parks. The panel includes an overview map of the trail with areas for customized information on the local community, including options for encased bulletin boards and a brochure holder.



Secondary Kiosk

- Simple Two Post Sign
- 32"Wide x 36"Tall Modular Display Area
- Single or Double Sided
- Direct Embedment of Posts
- Terrabilt Double Post Outboard

The secondary kiosk would be located at points of interest along the trail, such as parks, and would include an overview map of the trail on the front panel. There is also an option to provide customized local information on the back side of the panel.



Destination Sign

- Head-up Navigation While On Trail
- Shows Next Three Trail Towns or Major Parks
- Lists Distances and Amenities
- Used Sparingly (when exiting a major park or trail town)



Trail Parking

- Designated areas in trail towns and major parks for motorists to park and access the trail
- · Easy access to the trail
- · Ample parking available
- Access to amenities such as restrooms, drinking fountains and bicycle repair stations would be idea



Services

- Support Services Near the Trail
- Places to Access the Trail



Routes

- Branding
- Directions
- Route Reinforcement
- Many Different Types







MMUTCD compliant signs for road Right-of-Ways



Confidence markers and stencils for sidewalks and pathways

Connecting Routes

- Local Bike Routes
- Directions to Nearby **Regional Trails**







Regulatory & Safety


- Signs and Pavement Markings
- Focus on Interactions **Between Motorists** and Trail Users
- Primarily at Intersections
- Many Different Types











For additional information on signs, see the <u>Signage</u> and Pavement <u>Marking Guide</u>.

Algonac

Web meeting with the Downriver Advisory Committee held on October 20, 2020.

Action Items for Near Term Routes

- Initiate road diet study with MDOT on M-29 between Nook Road and Liberty Street to incorporate bikeway within the existing curbs
- Initiate lane narrowing study with MDOT on M-29 between Liberty Street and State Street to incorporate bikeway within the existing curbs
- Explore options for providing local inland bicycle route through Algonac and Clay Twp providing a by-pass to M-29 and a loop route in the City
- Provide alternative Bridge to Bay Trail route along M-29 when the trail to Algonac State Park floods

Kiosk Locations and Trail Parking

- · Algonac Waterfront Park Principal Kiosk
- Smith Recreation Field Secondary Kiosk
- Algonac Lions Park Principal Kiosk and Trail Parking

Safety Issues

- Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.
- Numerous vegetation encroachments noted during fieldwork. See the Analysis Document for details.

Responsible Agency:

City of Algonac and MDOT

City of Algonac and MDOT

City of Algonac and Clay Twp

City of Algonac and Clay Twp

Responsible Agency:

Algonac

Algonac

Algonac

Algonac Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in Algonac. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the

When implementing the sign schedule, please note the following:

- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.

The scope of this project focuses on wayfinding signs between Algonac and Port Huron. As future sections of the Bridge to Bay Trail develop north of Port Huron and west of Algonac, signs will be expanded to those communities.



Recommendations for the Algonac section include:

2 **PRINCIPAL KIOSKS**

SECONDARY KIOSKS


DESTINATION SIGNS

TRAIL PARKING **SIGNS**

18 **ROUTE SIGNS**

REGULATORY/ SAFETY SIGNS

STENCILS/ **STICKERS**



*Option to use 24" stencils or 12" stickers

Principal Kiosk at Riverfront Park

- Large Roofed Sign
- 36" Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing North
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16'x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.



Secondary Kiosk at Pine Grove Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing Southeast
- Back of sign: Option to add local information
- Viewing Surface: Provide a 5'x 5' concrete pad in front of sign. If sign is two-sided, turn perpendicular to pathway and a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.





¹




Principal Kiosk at Lions Club Park

- Large Roofed Sign
- 36"Tall x 48"Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing West
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16' x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.



Locate kiosk near bicycle repair station









Burtchville Twp

No meetings have taken place with Burtchville Township. Recommendations have been verified with Township.

Action Items for Near Term Routes

- Where the paved shoulder is designated as a bike route, modify the edge line markings at intersections to be consistent with typical bike lane markings. Specifically, remove radius markings and eliminate paved shoulders to the right of designated right turn lanes.
- Explore options for providing nonmotorized connection along utility corridor between Lakeport State Park Campground and North Lakeport (Lakeshore Rd)
- Explore options for providing nonmotorized connection between Lakeport State Park Day Area and the shared use path on State Road

Kiosk Locations and Trail Parking

- Lakeport State Park Day Use Area Principal Kiosk
- Lakeport State Park Campground Kiosk type and locations TBD until trail route becomes more defined
- Burtchville Park Secondary Kiosk

Note: If trail parking signs are used for the State Park, need to indicate that passport is required

Burtchville Twp Sign Schedule

The following pages layout recommendations for Kiosk in Burtchville Twp. These kiosk location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

Recommendations for the Burtchville Twp section include:





The scope of this project focuses on wayfinding signs between Algonac and Port Huron. As future sections of the Bridge to Bay Trail develop north of Port Huron and west of Algonac, signs will be expanded to those communities.

Responsible Agency:

MDOT

Burtchville Twp & MDNR


Burtchville Twp & MDNR

Responsible Agency:

MDNR

MDNR

Burtchville Twp





Principal Kiosk at Lakeport State Park Day Area

- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing East
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16'x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.





Secondary Kiosk at Burchville Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing North
- Back of sign: Option to add local information
- Viewing Surface: Place along pathway or provide a 5' x 5' concrete pad in front of sign. If sign is two-sided, turn perpendicular to pathway and a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.



China Twp

No meetings have taken place with China Township. Recommendations have been verified with Township.

Action Items for Near Term Routes

 Explore options for providing trail connection to China Township Belle River Park on King Road, would require road crossing on King Road

Kiosk Locations and Trail Parking

- China Township Belle River Access Park Secondary Kiosk
- Parking lot at northeast corner of King Road and Recor Road Secondary Kiosk and Trail Parking
- Fred Moore Hwy and King Road Secondary Kiosk (decision point for Great Lake to Lake Trail, US Bike Route 20 and Bridge to Bay Trail)

Safety Issues

• Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.

Responsible Agency:

China Twp

Responsible Agency:

China Twp

China Twp

China Twp

China Twp Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in China Twp. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the

When implementing the sign schedule, please note the following:


- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.



Recommendations for the China Twp section include:

SECONDARY KIOSKS

ROUTE SIGNS REGULATORY/ **SAFETY SIGNS**





Secondary Kiosk at China Twp Belle River Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing North
- Back of sign: Option to add local information
- Viewing Surface: Place along pathway or provide a 5' x 5' concrete pad in front of sign. If sign is two-sided, turn perpendicular to pathway and a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.



Explore options for providing trail connection to China Township Belle River Park on King Road, would require road crossing on King Road









Clay Twp

Web meeting with the Downriver Advisory Committee held on October 20, 2020.

Action Items for Near Term Routes

- Explore options for providing local inland bicycle route through Algonac and Clay Twp providing a by-pass to M-29 and a loop route in the City
- Provide alternative Bridge to Bay Trail route along M-29 when the trail to Algonac State Park floods
- Explore options for providing local bike route on Harsens Island
- Coordinate with new county park in Clay Twp to provide amenities for bicycles, such as a bicycle repair station and drinking fountains
- Where the paved shoulder is designated as a bike route, modify the edge line markings at intersections to be consistent with typical bike lane markings. Specifically, remove radius markings and eliminate paved shoulders to the right of designated right turn lanes.

Kiosk Locations and Trail Parking

- Pearl Beach Pier Secondary Kiosk
- Clay Township Park Secondary Kiosk and Trail Parking
- New County Park in Clay Twp Principal Kiosk (Future)
- Brown's Field (Harsens Island) Principal Kiosk
- Algonac State Park Principal Kiosk

Safety Issues

- Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.
- Numerous vegetation encroachments noted during fieldwork. See the Analysis Document for details.

Responsible Agency:

City of Algonac and Clay Twp

City of Algonac and Clay Twp

Clay Twp

Clay Twp and St Clair County

MDOT

Responsible Agency:

Clay Twp

Clay Twp

St Clair County Parks

Clay Twp

MDNR

Clay Twp Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in Clay Twp. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

When implementing the sign schedule, please note the following:

- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.

The scope of this project focuses on wayfinding signs between Algonac and Port Huron. As future sections of the Bridge to Bay Trail develop north of Port Huron and west of Algonac, signs will be expanded to those communities.



Recommendations for the Clay Twp section include:

PRINCIPAL **KIOSKS**

SECONDARY KIOSKS

DESTINATION SIGNS

SERVICE SIGNS

10 **ROUTE SIGNS**

10 **REGULATORY/ SAFETY SIGNS**



Secondary Kiosk at Pearl Beach Pier

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail map facing North
- Back of sign: Option to add local information
- Viewing Surface: Place along edge of path or provide 5' x 5' concrete pad in front of sign. If sign is two-sided a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.





Secondary Kiosk at Clay Township Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail map facing East
- Back of sign: Option to add local information
- Viewing Surface: Place along edge of path or provide a 5' x 5' concrete pad in front of sign. If sign is two-sided a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.





Principal Kiosk Brown's Field on Harsen's Island

- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing South
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16'x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.






Principal Kiosk in future County Park


- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16'x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.




Location to be determined based on future park design







10/29/21 37




38 10/29/21

Principal Kiosk in Algonac State Park

- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing East
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16'x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.





Cottrellville Twp

No meetings have taken place with Cottrellville Township. Recommendations have been verified with Township.

Action Items for Near Term Routes

Where the paved shoulder is designated as a bike route, modify the edge line markings at intersections to be consistent with typical bike lane markings. Specifically, remove radius markings and eliminate paved shoulders to the right of designated right turn lanes.

Kiosk Locations and Trail Parking

None

Safety Issues

- Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.
- Numerous vegetation encroachments noted during fieldwork. See the Analysis Document for details.

Responsible Agency:

MDOT

Cottrellville Twp Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in CottrellvilleTwp. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

When implementing the sign schedule, please note the following:


- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.




Recommendations for the Cottrellville Twp section include:


DESTINATION SIGNS

12 ROUTE **SIGNS**



10/29/21 43







East China Twp

No meetings have taken place with East China Township. Recommendations have been verified with Township.

Action Items for Near Term Routes

- Repair topcoat seem on M-29 shoulder south of St Clair
- Work with St Clair to Explore options for providing local bike route on S
 Riverside Ave north of Bree Road as an alternative bike route to M-29 paved
 shoulders

Kiosk Locations and Trail Parking

• East China Twp Park - Principal Kiosk and Trail Parking

Safety Issues

• Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.

Responsible Agency:

MDOT

East China Twp and St Clair

Responsible Agency:

East China Twp

East China Twp Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in East China Twp. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

When implementing the sign schedule, please note the following:

- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.



Recommendations for the East China Twp section include:

1 **PRINCIPAL** KIOSKS


DESTINATION SIGNS


3 TRAIL PARKING **SIGNS**

12 **ROUTE SIGNS** **REGULATORY/** SAFETY SIGNS


STENCILS/ **STICKERS**


















O BREAKAWAY METAL POST *Option to use 24" stencils or 12" stickers


[☐] COMPOSITE LUMBER POST (4"X4")

Principal Kiosk in East China Twp Park


- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing South
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a $16' \times 10'$ concrete pad should be installed so both sides of the sign are wheelchair accessible.














10/29/21 61



Fort Gratiot Twp

No meetings have taken place with Fort Gratiot Township. Recommendations have been verified with Township.

Action Items for Near Term Routes

- Continue seeking funding for pathway connections along Black River Run and Kraft Road
- Provide wayfinding signs between Fort Gratiot Trails and Bridge to Bay Trail once pathway connection complete
- Continue to pursue an off-road trail connection to connect existing trails south of Cardigan Road to existing trails north of Metcalf Road (this will become the main Bridge to Bay Trail Route when complete)
- Reconfigure lane markings to provide paved shoulder on M-25 from intersection of Lakeshore Rd and 24th Ave 850 feet north to existing paved shoulder on M-25.

Kiosk Locations and Trail Parking

Fort Gratiot County Park - Principal Kiosk

Fort Gratiot Sign Schedule

The following pages layout recommendations for Kiosk in Fort Gratiot Twp. These kiosk location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

Recommendations for the Fort Gratiot Twp section include:



The scope of this project focuses on wayfinding signs between Algonac and Port Huron. As future sections of the Bridge to Bay Trail develop north of Port Huron and west of Algonac, signs will be expanded to those communities.

Responsible Agency:

Fort Gratiot Twp


Fort Gratiot Twp

Fort Gratiot Twp

MDOT

Responsible Agency:

St Clair County Parks





☐ COMPOSITE LUMBER POST (4"X4")

Principal Kiosk at Fort Gratiot County Park

- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing South
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16' x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.



Ira Twp

Web meeting with the Downriver Advisory Committee held on October 20, 2020.

Action Items for Near Term Routes

Where the paved shoulder is designated as a bike route, modify the edge line markings at intersections to be consistent with typical bike lane markings. Specifically, remove radius markings and eliminate paved shoulders to the right of designated right turn lanes.

Responsible Agency:

MDOT

Kiosk Locations and Trail Parking

- Ira Township Park Principal Kiosk and Trail Parking
- Waterworks Park Secondary Kiosk

Responsible Agency:

Ira Twp

Ira Twp

Ira Twp Sign Schedule

The following pages layout recommendations for Kiosk in Ira Twp. These kiosk location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

Recommendations for the Ira Twp section include:





The scope of this project focuses on wayfinding signs between Algonac and Port Huron. As future sections of the Bridge to Bay Trail develop north of Port Huron and west of Algonac, signs will be expanded to those communities.





Principal Kiosk at Ira Township Park

- Large Roofed Sign
- 36"Tall x 48"Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing West
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of signs. If the sign is two-sided a 16'x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.





Secondary Kiosk at Clay Township Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing South
- Back of sign: Option to add local information
- Viewing Surface: Place along edge of path or provide a 5' x 5' concrete pad in front of sign. If sign is two-sided it should be turned so it is perpendicular to the pathway and a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.



Marine City

Met with community stakeholders to discuss city bike loop and trail wayfinding on September 18, 2020.

Action Items for Near Term Routes

- Sign local bike route to downtown
- Coordinate trail kiosk with new water trailhead at S Belle River Ave and the **Belle River**

Kiosk Locations and Trail Parking

- King Road Park Secondary Kiosk
- Marine City Library Principal Kiosk and Trail Parking
- Mariner Park Secondary Kiosk
- Lighthouse Park Secondary Kiosk
- Metropolis Street Secondary Kiosk (may need to coordinate with St Clair County Road Commission to use property adjacent to the trail)

Safety Issues

Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.

Responsible Agency:

Marine City

Marine City

Responsible Agency:

Marine City

Marine City

Marine City

Marine City and St Clair **County Road Commission**

Marine City Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in Marine City. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

When implementing the sign schedule, please note the following:

- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.



Recommendations for the Marine City section include:

1 **PRINCIPAL** KIOSKS

SECONDARY KIOSKS

DESTINATION SIGNS

TRAIL PARKING SIGNS

2 **SERVICE SIGNS**


11 ROUTE **SIGNS**

CONNECTING **ROUTE SIGNS**

REGULATORY/ SAFETY SIGNS

4 STENCILS/ **STICKERS**






10/29/21 71

Secondary Kiosk at Mariner Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing South
- Back of sign: Option to add local information
- Viewing Surface: Place along edge of path or provide a 5' x 5' concrete pad in front of sign. If sign is two-sided, turn so it is perpendicular to path and a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.





Secondary Kiosk at Lighthouse Park

- Simple Two Post Sign
- 32"Wide x 36"Tall Modular Display Area
- Direct Embedment of Posts
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing West
- Back of sign: Option to add local information
- Viewing Surface: Place along edge of path or provide a 5'x 5' concrete pad in front of sign. If sign is two-sided a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.




Secondary Kiosk at Future Kayak Launch Site off Belle River Ave north of bridge


- Simple Two Post Sign
- 32"Wide x 36"Tall Modular Display Area
- Direct Embedment of Posts
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing West
- Back of sign: Option to add local information
- Viewing Surface: Place along edge of path or provide a 5' x 5' concrete pad in front of sign. If sign is two-sided a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.




Location to be determined, need to coordinate with future kayak launch site. Option to upgrade to Principal Kiosk if combining information with water trail.



☐ COMPOSITE LUMBER POST (4"X4")



☐ COMPOSITE LUMBER POST (4"X4")




Secondary Kiosk at King Road Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing South
- Back of sign: Option to add local information
- Viewing Surface: Place along edge of path or provide a 5' x 5' concrete pad in front of sign. If sign is two-sided a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.



A new mid-block crosswalk is recommended to connect the Park to the Middle School and Trail on the East side of King Road.



☐ COMPOSITE LUMBER POST (4"X4")




00 10/20/21


Principal Kiosk at Library

- Large Roofed Sign
- 36"Tall x 48"Wide Modular Display Areas
- Single or Double Sided
- **Requires Footing**
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing West
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of signs. If the sign is two-sided a 16'x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.





^{*}Option to use 24" stencils or 12" stickers




10/29/21 83

Secondary Kiosk at Metropolis Street

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing West
- Back of sign: Option to add local information
- Viewing Surface: Provide a 5' x 5' concrete pad in front of sign. If sign is two-sided a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.



May need to coordinate with St Clair County Road Commission to use property adjacent to the trail when locating trail kiosk.



COMPOSITE LUMBER POST (4"X4")

Marysville

Web meeting with advisory committee held on October 21, 2020.

Action Items for Near Term Routes

- 2020 TAP Grant was awarded for connections along River Road, south of Chrystler Beach, and along Davis Road. This includes a trail crossing at M-29.
- In addition to the TAP Grant, the City of Marysville plans to complete the shared use path connection between Marysville Park and Chrystler Beach. This connection includes a shared use path on the west side of River Road, south of Huron, with a new crosswalk to Chrystler Beach.

Kiosk Locations and Trail Parking

- Marysville Beach Secondary Kiosk
- Marysville City Park Secondary Kiosk
- Morton Park Principal Kiosk and Trail Parking

Safety Issues

 Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included. Responsible Agency:

Marysville, St Clair Twp and MDOT

Responsible Agency:

Marysville

Marysville

Marysville

Marysville Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in Marysville. These sign locations have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

When implementing the sign schedule, please note the following:

- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.



Recommendations for the Marysville section:

PRINCIPAL KIOSKS

SECONDARY KIOSKS

4 **DESTINATION** SIGNS


TRAIL PARKING SIGNS

SERVICE SIGNS


46 **ROUTE SIGNS**

CONNECTING **ROUTE SIGNS**


26 REGULATORY/ **SAFETY SIGNS** STENCILS/ **STICKERS**




88 10/29/21




10/29/21 89




☐ COMPOSITE LUMBER POST (4"X4") *Option to use 24" stencils or 12" stickers




^{*}Option to use 24" stencils or 12" stickers



^{*}Option to use 24" stencils or 12" stickers



^{*}Option to use 24" stencils or 12" stickers




COMPOSITE LUMBER POST (4"X4") *Option to use 24" stencils or 12" stickers




Secondary Kiosk at Chrysler Beach

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing west
- Back of sign: Option to add local information
- Viewing Surface: Place along pathway or provide a 5'x 5' concrete pad in front of sign. If sign is two-sided a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.





^{*}Option to use 24" stencils or 12" stickers




^{*}Option to use 24" stencils or 12" stickers


Secondary Kiosk at Marysville Park


- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- **Direct Embedment of Posts**
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map
- Back of sign: Option to add local information
- Viewing Surface: Place along pathway or provide a 5'x 5' concrete pad in front of sign. If sign is two-sided a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.







COMPOSITE LUMBER POST (4"X4")






102 10/29/21





COMPOSITE LUMBER POST (4"X4")





Principal Kiosk at Morton Park


- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- Requires Footing
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing West
- Back of sign: Option to add additional information, such as St Clair County Community College events or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16' x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.
















10/29/21 111







114 10/29/21

New Baltimore

No meetings have taken place with New Baltimore. Recommendations have not been verified with City.

Action Items for Near Term Routes

- Provide local bike route wayfinding signs between the Bridge to Bay Trail and Walter & Mary Burke Park
- Repair paved shoulder on M-29 east of County Line Road, pavement in poor condition

Kiosk Locations and Trail Parking

• Walter and Mary Burke Park - Secondary Kiosk

New Baltimore Sign Schedule

The following pages layout recommendations for Kiosk in New Baltimore. These kiosk location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

Recommendations for the New Baltimore section include:



The scope of this project focuses on wayfinding signs between Algonac and Port Huron. As future sections of the Bridge to Bay Trail develop north of Port Huron and west of Algonac, signs will be expanded to those communities.

Responsible Agency:


New Baltimore

MDOT

Responsible Agency:

New Baltimore





Secondary Kiosk at Walter & Mary Burke Park

- Simple Two Post Sign
- 32"Wide x 36"Tall Modular Display Area
- Direct Embedment of Posts
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing Northwest
- Back of sign: Option to add local information
- Viewing Surface: Place along pathway or provide a 5'x 5' concrete pad in front of sign. If sign is two-sided a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.



Port Huron

In-person meeting with advisory committee held on October 27, 2020 and web meeting with advisory committee held on December 9, 2020.

Action Items for Near Term Routes

- Seek funding for pathway along Gratiot Ave to connect to planned trail along Black River Run
- Provide a safe and accessible bicycle and pedestrian connection to Lakeside Park from the Bridge to Bay Trail Route
- Explore potential trail connection at south end of 7th Street
- Explore potential road diet on Thomas Edison Parkway to incorporate bikeway or adding shared lane markings within the existing curbs
- Explore switching Electric Ave to Military Street by incorporate a bikeway within the existing curbs through a road diet

Kiosk Locations and Trail Parking

- Lakeside Park Principal Kiosk and Trail Parking
- Lighthouse Park Principal Kiosk and Trail Parking
- Blue Water Bridge Park Principal Kiosk and Trail Parking
- Pinegrove Park Secondary Kiosk
- Quay Street & Fort Street Secondary Kiosk
- Blue Water River Walk Principal Kiosk
- Wetlands County Park Secondary Kiosk and Trail Parking
- 10th Street Secondary Kiosk
- Lincoln Park Secondary Kiosk and Trail Parking
- Intersection of 10th Street and Shared Use Path Secondary Kiosk

Safety Issues

- Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.
- Numerous pavement surface and trip hazards issues were noted during fieldwork. See the Analysis Document for details.

Responsible Agency:

Port Huron

Port Huron

Port Huron

Port Huron

Port Huron & MDOT

Responsible Agency:

Port Huron

Port Huron

Port Huron

Port Huron

Port Huron

Community Foundation of St Clair County

St Clair County Park

Port Huron

Port Huron

Port Huron

Port Huron Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in Port Huron. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

When implementing the sign schedule, please note the following:

- Older practices often included signs that were not warranted.
 These signs are not inherently problematic or dangerous, but
 unnecessary. In many cases the existing signage was close
 enough to proposed guidelines that they are preserved in
 place. To reduce sign clutter and unnecessary costs, at the
 end of life these signs should be removed and replaced with
 recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.




Recommendations for the Port Huron section include:

3 PRINCIPAL KIOSKS 5 SECONDARY KIOSKS **7**DESTINATION
SIGNS

4 TRAIL PARKING SIGNS 66 ROUTE SIGNS


16
CONNECTING
ROUTE SIGNS

5 REGULATORY/ SAFETY SIGNS 68 STENCILS/ STICKERS





O BREAKAWAY METAL POST

[☐] COMPOSITE LUMBER POST (4"X4")



10/29/21







*Option to use 24" stencils or 12" stickers



*Option to use 24" stencils or 12" stickers



*Option to use 24" stencils or 12" stickers



O BREAKAWAY METAL POST
*Option to use 24" stencils or 12" stickers

Secondary Kiosk at 10th Street

- Simple Two Post Sign
- 32"Wide x 36"Tall Modular Display Area
- Direct Embedment of Posts
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing West
- Back of sign: Option to add local information
- Viewing Surface: Provide a 5' x 5' concrete pad in front of sign. If sign is two-sided a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.




Secondary Kiosk at Wetlands County Park

- Simple Two Post Sign
- 32"Wide x 36"Tall Modular Display Area
- Direct Embedment of Posts
- · Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing Northwest
- Back of sign: Option to add local information
- Viewing Surface: Place along pathway or provide a 5' x 5' concrete pad in front of sign. If sign is twosided, turn so it is perpendicular to pathway and a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.





*Option to use 24" stencils or 12" stickers



^{*}Option to use 24" stencils or 12" stickers



Principal Kiosk at entrance to the Blue Water River Walk


- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- Requires Footing
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing East
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16' x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.




Secondary Kiosk at northwest corner of Quay St and Fort St


- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- Direct Embedment of Posts
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing Southeast
- Back of sign: Option to add local information
- Viewing Surface: Place existing concrete pad. If sign is two-sided it should be installed so both sides of the sign are visibile from the sidewalk and wheelchair accessible.







*Option to use 24" stencils or 12" stickers






*Option to use 24" stencils or 12" stickers





*Option to use 24" stencils or 12" stickers







Secondary Kiosk at Pine Grove Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- Direct Embedment of Posts
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing South
- Back of sign: Bridge to Bay Trail Map facing North
- Viewing Surface: Place along pathway or provide a 5'x 5' concrete pad in front of sign. Sign is twosided and should turn perpendicular to pathway with a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.





*Option to use 24" stencils or 12" stickers



^{*}Option to use 24" stencils or 12" stickers



*Option to use 24" stencils or 12" stickers

Secondary Kiosk at Blue Water Bridge Park


- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- Direct Embedment of Posts
- · Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map facing South
- Back of sign: Option to add local information
- Viewing Surface: Place along pathway or provide a 5' x 5' concrete pad in front of sign. If sign is two-sided, turn perpendicular to pathway with a 10' x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.




Principal Kiosk at Lighthouse Park


- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- Requires Footing
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing North
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities like the Great-Lake-to-Lake Trail.
- Viewing Surface: Place along pathway or provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided, turn so sign is perpendicular to pathway and a 16' x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.











146 10/29/21

Principal Kiosk at Lakeside Park

- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- Requires Footing
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing West
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16' x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.



St Clair

Web meeting with advisory committee held on October 13, 2020.

Action Items for Near Term Routes

- Where the paved shoulder is designated as a bike route, modify the
 edge line markings at intersections to be consistent with typical bike
 lane markings. Specifically, remove radius markings and eliminate paved
 shoulders to the right of designated right turn lanes.
- Repair topcoat seam on shoulder of M-29/Oakland Ave
- Coordinate with MDOT on road diet on M-29 south of Clinton Ave
- Work with East China Twp to explore options for providing local bike route on S Riverside Ave north of Bree Road as an alternative bike route to M-29 paved shoulders
- Continue seeking funding for planned bikeway on Clinton Street

Kiosk Locations and Trail Parking

- Greig Park Principal Kiosk and Trail Parking
- St Clair BMX and Skate Park Secondary Kiosk
- Rotary Park Secondary Kiosk
- · Palmer Park Principal Kiosk
- St Clair Mall Trail Parking

Outstanding Issues

• Seeking permission to use mall near riverfront as a designated Trail parking location

Safety Issues

• Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.

Responsible Agency:

MDOT

MDOT

MDOT and St Clair

St Clair and East China Twp

St Clair

Responsible Agency:

St Clair

St Clair

St Clair

St Clair

St Clair

Responsible Agency:

St Clair

St Clair Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in St Clair. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

When implementing the sign schedule, please note the following:

- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.



Recommendations for the St Clair section include:


2 PRINCIPAL KIOSKS

1 SECONDARY KIOSKS 2 DESTINATION SIGNS 4 TRAIL PARKING SIGNS **2** SERVICE SIGNS

17 ROUTE SIGNS


2CONNECTING
ROUTE SIGNS


4 STENCILS/ STICKERS



150 10/29/21













10/29/21 155

Principal Kiosk at Greig Park

- Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- · Single or Double Sided
- Requires Footing
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing Southeast
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities such as the Great-Lake-to-Lake Trail.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16' x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.







O BREAKAWAY METAL POST
*Option to use 24" stencils or 12" stickers

Principal Kiosk at Palmer Park

- · Large Roofed Sign
- 36"Tall x 48" Wide Modular Display Areas
- Single or Double Sided
- Requires Footing
- Terrabilt 2-Post Classic Kiosk
- Front of sign: Bridge to Bay Trail map with local trail information facing West
- Back of sign: Option to add additional information, such as water trail or other recreation opportunities.
- Viewing Surface: Provide a 15'x 6' concrete pad in front of sign. If the sign is two-sided a 16'x 10' concrete pad should be installed so both sides of the sign are wheelchair accessible.




Secondary Kiosk at Rotary Park

- Simple Two Post Sign
- 32" Wide x 36" Tall Modular Display Area
- Direct Embedment of Posts
- Terrabilt Double Post Outboard
- Front of sign: Bridge to Bay Trail Map
- Back of sign: Water trail information
- Viewing Surface: Turn two-sided sign perpendicular to pathway and a 10'x12' concrete pad should be installed so both sides of the sign are wheelchair accessible.

Coordinate with Kayak Launch improvements and water trail maps, may utilitized new kiosk or existing structure



Combined Water Trail / Land Trail Kiosk





10/29/21 161

St Clair Twp

No meetings have taken place with St Clair Township. Recommendations have been verified with Township.

Action Items for Near Term Routes

- Repair trail in construction area
- Work with Marysville to complete connection to River Road; pending Marysville TAP grant submission

Kiosk Locations and Trail Parking

None planned

Safety Issues

• Detectable warnings are required at every intersection with a roadway and desirable at every major driveway. The sign schedule notes locations where detectable warnings should to be included.

Responsible Agency:

St Clair Twp
St Clair Twp

St Clair Twp Sign Schedule

The following pages layout recommendations for signs along the Bridge to Bay Trail in St Clair Twp. These sign location have also been inventoried in a GIS database. Contact Sheri Faust for access to the data.

When implementing the sign schedule, please note the following:

- Older practices often included signs that were not warranted. These signs are not inherently problematic or dangerous, but unnecessary. In many cases the existing signage was close enough to proposed guidelines that they are preserved in place. To reduce sign clutter and unnecessary costs, at the end of life these signs should be removed and replaced with recommended signs from the signage and wayfinding guide.
- Do the ongoing upkeep of pavement markings, this plan notes all pavement markings, whether they are currently existing or not.



Recommendations for the St Clair Twp section include:

DESTINATION SIGNS

7ROUTE
SIGNS

16
REGULATORY/
SAFETY SIGNS







